



Del Mar Analytical

2852 Alton Ave., Irvine, CA 92606 (949) 261-1022 FAX (949) 261-1228
1014 E. Cooley Dr., Suite A, Colton, CA 92324 (909) 370-4667 FAX (909) 370-1046
7277 Hayvenhurst, Suite B-12, Van Nuys, CA 91406 (818) 779-1844 FAX (818) 779-1843
9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 (858) 505-8596 FAX (858) 505-9689
9830 South 51st St., Suite B-120, Phoenix, AZ 85044 (480) 785-0043 FAX (480) 785-0851
2520 E. Sunset Rd. #3, Las Vegas, NV 89120 (702) 798-3620 FAX (702) 798-3621

STL Los Angeles
1721 S. Grand Avenue
Santa Ana, CA 92705
Attention: Diane Suzuki

Project ID: E2H090172

Report Number: CLH0177

Sampled: 08/08/02
Received: 08/14/02

CASE NARRATIVE

| LABORATORY NUMBER | SAMPLE DESCRIPTION | SAMPLE MATRIX | ANALYSES |
|----------------------|--------------------------|------------------|----------|
| CLH0177-01 | COM-SP-006-SSA080802-001 | Soil | EPA 8310 |
| CLH0177-02 | COM-SP-003-SSA080802-001 | Soil | EPA 8310 |

SAMPLE RECEIPT: Samples were received intact, at 3°C, and with chain of custody documentation.

HOLDING TIMES: Holding times were met.

PRESERVATION: Samples requiring preservation were verified prior to sample analysis.

QA/QC CRITERIA: All analyses met method criteria, except as noted in the report with data qualifiers.

COMMENTS: No significant observations were made.

SUBCONTRACTED: The 8310 analysis was subcontracted to Del Mar Analytical, Phoenix, AZ (ELAP #2446). The extraction for this analysis was performed at Del Mar Analytical, Colton, CA.

DEL MAR ANALYTICAL, COLTON (CA ELAP #1169)

Del Mar Analytical, Colton
Jeanne Shoulder For Clifton J. Kiser
PM Supervisor

The results pertain only to the samples tested in the laboratory. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical.

CLH0177 <Page 2 of 8>

BOE-C6-0231581